

v0.4 - January 24th, 2022



General

- Follow the instructions carefully in chronologic order as the instruction obtains important steps in correct sequence for having a smooth assembly experience
- Treat all parts with special care. There's a risk for cosmetic damage during the assembly process which we do not want you to occur.
- Tighten all screws firmly, but do not overtighten them. Overtightening might cause damage to screws, nuts, threads as well as cosmetic damage to aluminium and HPL parts.
- If you encounter any issues or have any questions regarding our products, contact us at support@overpower.gg. We are happy to help you!




Preparation


- Find yourself enough space for the assembly process
- Find a carpet or other soft surface to assembly on
- The assembly will take approximately 30 minutes, reserve enough time to assembly the product on one go
- After opening the package, check the parts received and compare them to the part list to make sure you have received all the parts for the product
 - In case there's a part missing, contact us at support@overpower.gg


OverPower

Part list

- 3030 slide M8, 4 pcs, (A)
- Actuator control panel, (C)
- Actuator power supply, (D)
- Corner bracket, 2pcs, (E)
- Linear actuator, (F)
- M8x12, 2pcs, (G)
- M8x40, 4pcs, (I)
- Roll-in T-nut, 2pcs, (J)
- Screws and nuts for control panel, (K)







OverPower



Insert the M8x40 with sleeve to actuator

OverPower



Attach the actuator to the cross support with the slide and bolt from the previous phase

